

C A S E S T U D Y

Comprehensive Indoor Environmental Health Quality Management by Saniservice

SANI
SERVICE
The Swiss Concept of Indoor Environments

INDOOR SCIENCES
By Saniservice

This case study examines how Saniservice successfully resolved severe indoor air quality issues in a luxury apartment on Palm Jumeirah. The client, Ms. Fatima R., experienced persistent allergic reactions when inside her home, which were traced to multiple environmental contaminants. Through comprehensive testing, specialized cleaning protocols, and innovative remediation techniques, Saniservice transformed the indoor environment into a healthy living space, eliminating the client's allergic symptoms and ensuring long-term air quality improvement.

Introduction

Background of the Case

Ms. Fatima R. resides in an upscale three-bedroom apartment on Palm Jumeirah, one of Dubai's most prestigious residential areas. In recent months, she began experiencing increasingly severe allergic reactions whenever she spent time in her home. These symptoms included persistent sneezing, watery eyes, nasal congestion, and occasional skin rashes. Notably, her symptoms would significantly improve whenever she left her apartment for extended periods.

After consulting with several medical specialists, including an allergist who suggested environmental factors might be contributing to her condition, Ms. Fatima attempted conventional solutions. She hired a standard cleaning service and purchased several air purifiers, but her symptoms persisted. Frustrated with these ineffective measures, she contacted Saniservice for a professional assessment of her indoor environment.

Objectives

The primary objectives of this case study are:

1. To document the comprehensive testing methodology employed by Saniservice.
2. To detail the specialized cleaning and remediation protocols implemented.
3. To evaluate the measurable improvements in indoor air quality and their impact on the client's health.
4. To highlight the importance of professional environmental quality management in residential settings.

Assessment and Diagnostic Testing

Testing Methodology

Saniservice's Indoor Sciences Department conducted a thorough environmental assessment of Ms. Fatima's apartment, focusing on:

1. **Air Quality Testing:** Multiple air samples were collected throughout the apartment using specialized equipment to detect airborne mold spores, mycotoxins, and other allergens.
2. **Surface Sampling:** Swab samples were taken from various surfaces, particularly around air conditioning vents and within ductwork, to identify potential contamination sources.

- Mattress and Upholstery Testing:** Specialized vacuum sampling was performed on mattresses, bedding, upholstered furniture, and carpets to quantify dust mite allergen concentrations.
- Moisture Mapping:** Infrared thermal imaging was used to detect any hidden moisture issues that could contribute to mold growth.

Findings

The comprehensive testing revealed multiple environmental issues:

- Airborne Mycotoxins:** Elevated levels of aflatoxin (a metabolite produced by *Aspergillus* species) were detected in air samples, with concentrations particularly high in bedrooms and the living area.
- AC System Contamination:** Inspection of the air conditioning system identified significant mold growth within the ductwork and on cooling coils. This was determined to be the primary source of airborne aflatoxin.
- Dust Mite Allergens:** Analysis of mattress samples revealed extremely high concentrations of dust mite allergens (Der p 1 and Der f 1), exceeding recommended thresholds by over 300%.
- General Dust Accumulation:** Higher than normal levels of general dust and particulate matter were found throughout the apartment, exacerbating Ms. Fatima's allergic responses.

The table below summarizes the key findings from the testing:

Contaminant	Location	Measured Level	Threshold Level
Aflatoxin B1	Indoor Air	85 ng/m ³	<20 ng/m ³
Dust Mite Allergens	Mattress	12 µg/g dust	<2 µg/g dust
Mold Spores	AC Ducts	8,500 CFU/m ³	<500 CFU/m ³

Intervention Plan

Based on these findings, Saniservice developed a comprehensive intervention plan consisting of two main components:

- Full AC System Cleaning:** A thorough cleaning and disinfection of the entire air conditioning system to eliminate the source of airborne aflatoxin.
- Hygienization Deep Cleaning:** Saniservice's premium deep cleaning service targeting all surfaces, fabrics, and furnishings to remove allergens and create a hypoallergenic environment.

Implementation: AC System Cleaning

Saniservice technicians performed a comprehensive AC system cleaning according to the company's rigorous standards:

1. **System Inspection:** A detailed visual inspection using specialized cameras identified areas of contamination within the ductwork, cooling coils, and air handling units.
2. **Duct Cleaning:** High-powered vacuum equipment with HEPA filtration was used to remove accumulated dust and debris from ductwork. Robotic brushing systems reached areas that conventional cleaning methods cannot access.
3. **Coil Cleaning:** The AC units were partially disassembled to access evaporator coils, which were cleaned using specialized antimicrobial solutions and pressure washing techniques.
4. **Blower and Fan Cleaning:** Blower assemblies and fan components were removed, cleaned, sanitized, and rebalanced to ensure optimal performance.
5. **Drainage System Treatment:** Condensate drain pans and lines were thoroughly cleaned and treated with enzyme-based solutions to prevent future biofilm growth.
6. **Antimicrobial Treatment:** The entire system received an EPA-registered antimicrobial fogging treatment to eliminate residual microorganisms and prevent recontamination.

This comprehensive approach ensured that all components of the AC system were thoroughly cleaned, addressing the primary source of mycotoxin contamination.

Implementation: Hygienization Deep Cleaning

Following the AC system cleaning, Saniservice performed their signature Hygienization Deep Cleaning, which goes beyond conventional cleaning methods:

The Hygienization Protocol

As noted in the Saniservice materials, "Hygienization refers to the comprehensive restoration of your indoor environment's cleanliness, reaching its most profound aspects. This optimal state of hygiene is meticulously designed by experts, providing a solid foundation for establishing the regular cleaning routine necessary to maintain a pristine and healthy space"¹.

The process included:

1. **Surface-Specific Treatments:** Unlike standard cleaning that uses the same products for all surfaces, Hygienization employs specialized solutions for different materials (wood, metal, fabric, etc.), ensuring effective cleaning without damage.
2. **Multi-Layer Cleaning:** Each surface underwent a three-phase cleaning process:
 - Deep cleaning to remove visible and embedded contaminants
 - Sanitization to eliminate microorganisms
 - Protective treatment to prevent recontamination

3. **Mattress Remediation:** Ms. Fatima's mattresses received specialized treatment:
 - Deep vacuum extraction using HEPA-filtered equipment
 - Hot water extraction cleaning to remove embedded allergens
 - UV-C light treatment to kill dust mites
 - Application of anti-allergen barrier spray
4. **Upholstery and Soft Furnishings:** All fabric surfaces underwent similar comprehensive treatment to eliminate dust mite allergens.
5. **Floor Treatments:** Different flooring surfaces received appropriate deep cleaning:
 - Carpets: Hot water extraction with anti-allergen treatment
 - Hard floors: Multi-phase cleaning with specialized equipment to reach grout lines and corners
6. **Wall and Ceiling Cleaning:** Often overlooked in standard cleaning, walls and ceilings were professionally cleaned to remove airborne particulate matter that had settled on vertical surfaces.
7. **Air Purification:** During and after cleaning, HEPA air scrubbers were operated throughout the apartment to capture airborne particles released during the cleaning process.

Distinguishing Factors of Hygienization

The Hygienization Deep Cleaning protocol distinguishes itself from standard cleaning services in three key dimensions:

1. **Deeper:** Penetrates beyond surface cleaning to remove embedded contaminants from within materials.
2. **Wider:** Addresses all surfaces in the home, including often-overlooked areas such as curtains, underneath furniture, light fixtures, and HVAC vents.
3. **More Surface-Specific:** Employs specialized techniques and solutions tailored to each type of surface material, ensuring effective cleaning without damage.

Results and Outcomes

Post-Intervention Testing

Two weeks after completing the AC cleaning and Hygienization Deep Cleaning, Saniservice conducted follow-up testing to assess the effectiveness of their interventions:

Contaminant	Before Intervention	After Intervention	Reduction (%)
Aflatoxin B1	85 ng/m ³	< 5 ng/m ³	> 94%
Dust Mite Allergens	12 µg/g dust	0.8 µg/g dust	> 93%

Client Health Improvement

Ms. Fatima reported significant improvements in her health after the Saniservice intervention:

- Complete elimination of allergic symptoms when at home
- Improved quality of sleep
- No recurrence of skin rashes
- Reduced dependency on allergy medications

In a follow-up interview, Ms. Fatima stated: "I had no idea that my beautiful home was making me sick. The difference after Saniservice's work is remarkable—I can finally enjoy being in my apartment without constantly sneezing or feeling unwell."

Discussion

Comprehensive Approach to Indoor Environmental Health

This case study demonstrates the importance of addressing multiple aspects of indoor environmental health. While many service providers might have focused solely on either the AC system or general cleaning, Saniservice's comprehensive approach identified and remediated all contributing factors to Ms. Fatima's allergic reactions.

The Persistence of Allergens

Standard cleaning methods often fail to adequately address allergens such as dust mites and mycotoxins because:

1. Dust mites burrow deep into mattresses and upholstery, beyond the reach of conventional vacuum cleaners.
2. Mycotoxins can adhere to surfaces even after visible mold has been removed.

3. AC systems continuously circulate contaminants throughout the home if not properly cleaned.

The Hygienization Deep Cleaning protocol specifically addresses these challenges through its deeper, wider, and surface-specific approach.

Preventive Measures and Long-Term Solutions

Following the intervention, Saniservice provided Ms. Fatima with recommendations for maintaining her newly hygienic environment:

1. Quarterly AC maintenance to prevent recontamination
2. Use of allergen-proof mattress and pillow covers
3. Regular HEPA vacuum cleaning of soft furnishings
4. Maintaining optimal indoor humidity levels (40-60%)

Conclusion

This case study highlights the critical importance of professional indoor environmental quality management in addressing complex allergen-related health issues. Through the application of advanced testing methodologies, specialized cleaning protocols, and innovative remediation techniques, Saniservice successfully transformed Ms. Fatima's contaminated living space into a healthy environment.

The case demonstrates how Saniservice's signature Hygienization Deep Cleaning protocol, combined with comprehensive AC system cleaning, provides a superior solution to indoor air quality challenges compared to conventional cleaning methods. By addressing both visible and hidden contaminants, Saniservice not only relieved Ms. Fatima's immediate symptoms but also created conditions for long-term environmental health.

For individuals experiencing unexplained allergic reactions at home, this case underscores the value of professional assessment and remediation of the indoor environment as an essential component of a comprehensive health management strategy.

References:

1. Saniservice. (2025). *A Deeper Deep Cleaning - Hygienization by Saniservice*. Retrieved from <https://saniservice.com/deep-cleaning/>
2. Investigation of Indoor Air Quality inside Houses From UAE. (2025).
3. EPA. (2024). *Indoor Air Quality Guidelines for Residential Buildings*.
4. American Academy of Allergy, Asthma & Immunology. (2024). *Dust Mite Allergen Thresholds and Health Effects*.
5. Institute of Inspection Cleaning and Restoration Certification. (2023). *Standard and Reference Guide for Professional Mold Remediation*.
6. Journal of Environmental Health. (2025). *Mycotoxins in Indoor Environments: Occurrence, Health Effects, and Remediation Strategies*.
7. World Health Organization. (2024). *Guidelines for Indoor Air Quality: Dampness and Mould*.
8. Saniservice. (2025). *AC Cleaning Standards and Protocols*. Retrieved from www.saniservice.com/fact-sheet/